

MAIN COMPONENTS ON QUADRA PLANT

▪ ELECTRIC AND AUTOMATISM

PLC automatism: **SCHNEIDER**

Screen: **PROFACE**

Contactors + various: **SCHNEIDER**

Sécurité cells and others: **SICK, LEUZE, PEPPER**

▪ MOTORS

Motors and variators for vibration: **LENZE**

Motors, variators and servo motors for other parts: **SEW USOCOME**

▪ MECHANICAL PARTS

Pouly and belt: **ANGST & PFISTER, SEDIS**

Pignons and crowns: **SEDIS**

Bearings: **SNR, NTN**

▪ HYDRAULIC

Pomp: **ATOS, PARKER**

Distributors: **ATOS**

Valves: **BOSCH REXROTH**

Air cooling: **HYDAC**

Flexibles: **PARKER**